

Greenhorn Creek Integrated Restoration Project Construction 2015



Reid Dam Fish Passage Construction, Aug 2015



Volunteer, Megan Stewart, moving fish from below the Reid Dam.



Sediment water quality control dam below construction of fish passage structure at Reid Dam.

Moving rock and fill for fish passage structure.





Fish passage structure looking upstream at dam.



Fish passage structure looking downstream from dam.



Farnworth Bank
Stabilization
Construction,
August 2015



Boulder vane and bank at Farnworth.